

INSPECTION REPORT

End of contract

GENERAL INFO

File	321765
License plate	QF9350
Vehicle identification number	KMHS4812DPU088111
Dossier	2022034026
Make	Hyundai Santa Fe 180 PHEV Shin
Mileage	77645
First registration	01/09/2023
client availability date	08/09/2026
inspectionDate	10/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	N
310	Wheel Two Tone Front Left // Repair	Y
411	Seat Front Left // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
560	Interior / A Pillar Cover / Replace	N

Damage Pictures



Wheel Two Tone Front Left // Repair-scratch



Bumper Rear // Painting-scratch



Seat Front Left // Repair-scratch




Seat Front Left / Bottom Coating / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Door Front Left // Smart Repair Small-dent



Interior / A Pillar Cover / Replace-Incinerated



Windshield // Replace-glass damage