

INSPECTION REPORT


End of contract

GENERAL INFO

File	305869
License plate	2EVK821
Vehicle identification number	JTDKBABB90A290935
Dossier	2023177158
Make	Toyota Yar.Cr.1.5 Hyb.85kw Dyn
Mileage	56219
First registration	09/02/2024
client availability date	17/02/2026
inspectionDate	17/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Damage within Renta-norm-



Bumper Front / Spoiler / Replace-scratch + dent



Interior Cleaning // Small-stain