

INSPECTION REPORT


End of contract

GENERAL INFO

File	320164
License plate	2AWG976
Vehicle identification number	W1N1671171A530874
Dossier	2021 013 005
Make	Mercedes GLE 350 de 4M Bus.Sol
Mileage	199965
First registration	13/08/2021
client availability date	12/08/2026
inspectionDate	27/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	N
237	Wing Front right / Trim / Replace	N
272	Bumper Front / Trim Right / Replace	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
117	Wing Rear Left / Trim / Replace	N
136	Bumper Rear // Polish	Y
187	Wing Rear Right / Trim / Replace	N
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	Y
413	Seat Front Left / Rear Coating / Replace	Y

Damage Pictures



Door Rear Right // Painting-scratch



Wing Rear Right / Trim / Replace-scratch




Bumper Rear // Polish-scratch




Wing Rear Left / Trim / Replace-scratch





Rocker Panel Left // Smart Repair Medium-dent



Door Front Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Seat Front Left / Rear Coating / Replace-worn



Door Front Left // Smart Repair Small-scratch



Front Bonnet // Painting-scratch



Bumper Front // Painting-scratch



Bumper Front / Trim Right / Replace-scratch



Wing Front right / Trim / Replace-scratch