

INSPECTION REPORT

End of contract

GENERAL INFO

File	318434
License plate	2ADC264
Vehicle identification number	VSKCTND23U0156769
Dossier	2020209029
Make	Nissan Navara 2.3dCi DC 4x4 16
Mileage	156235
First registration	24/02/2021
client availability date	24/07/2026
inspectionDate	12/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
194	Door Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	N
891	Lettering Removal 15min	N
15	Bumper Front // Replace & Painting	N
33	Front Bonnet // Repair & Painting	N
64	Wing Front Left // Repair & Painting	N
76	Side View Mirror Left / Shell / Replace Painted	Y
84	Door Front Left // Repair & Painting	Y
92	Rocker Panel Left // Painting	N
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	Y
134	Bumper Rear // Repair & Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
142	Back Side // Repair & Painting	Y
143	Back Side // Replace & Painting	N
162	Roof // Painting	Y
174	Light / Rear Right / Replace	N
186	Wing Rear Right // Polish	Y
202	Rocker Panel Right // Painting	N
227	Side View Mirror Right / Shell / Replace Not Painted	Y
236	Wing Front right // Polish	Y
244	Light / Front Right / Replace	Y
271	Bumper Front / Trim Left / Replace	Y
274	Bumper Front / Grid Central / Replace	N
412	Seat Front Left / Bottom Coating / Replace	N
540	Interior // Repair 1	N
541	Interior // Repair 2	N
564	Dashboard // Replace Completely	Y
614	Front Left Door Interior Coating // Replace Completely	N

621	Front Right Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	Y
840	Interior Cleaning // Large	N

Damage Pictures



Bumper Front / Trim Left / Replace-bad position



Dashboard // Replace Completely-hole







Interior Cleaning // Large-Splashes



Back Side // Repair & Painting-bad repair



Bumper Front // Replace & Painting-cracked



Front Left Door Interior Coating // Replace Completely-cracked



Light / Rear Right / Replace-cracked



Bumper Front / Grid Central / Replace-cracked




Front Right Door Interior Coating // Repair-Incinerated



Interior // Repair 1-Incinerated



Seat Front Left / Bottom Coating / Replace-Incinerated




Interior // Repair 2-Incinerated



Bumper Rear / Lower Cover Not Painted / Replace-rust



Wing Rear Right // Polish-Chemical reaction




Roof // Painting-Chemical reaction



Rear Right Door Interior Coating // Repair-scratch



Door Rear Left // Painting-scratch



Light / Rear left / Replace-scratch



Rocker Panel Right // Painting-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Wing Front right // Polish-scratch



Light / Front Right / Replace-scratch



Side View Mirror Left / Shell / Replace Painted-scratch




Front Bonnet // Repair & Painting-dent



Bumper Rear // Repair & Painting-dent



Back Side // Replace & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Rocker Panel Left // Painting-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Lettering Removal 15min-Remainder stickers