

INSPECTION REPORT

End of contract

GENERAL INFO

File	309715
License plate	SQ1009
Vehicle identification number	ZACNJECS2MPR65727
Dossier	2022039009
Make	Jeep Compass 1.6MJD 131 Limite
Mileage	72378
First registration	30/03/2022
client availability date	01/04/2026
inspectionDate	09/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	Y
213	Door Front Right // Painting	Y
83	Door Front Left // Painting	N
103	Door Rear Left // Painting	N
35	Front Bonnet // Polish	Y
64	Wing Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
114	Wing Rear Left // Repair & Painting	Y
136	Bumper Rear // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Bumper Rear // Polish-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Front Bonnet // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Front Right // Painting-bad repair



Door Rear Right // Painting-bad repair



Wing Rear Right // Painting-bad repair



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch