

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	311592
License plate	EY2020
Vehicle identification number	W1KAH4GB6PF109586
Dossier	2022298011
Make	Mercedes C Break 300 259 AMG L
Mileage	56604
First registration	24/07/2023
client availability date	27/04/2026
inspectionDate	29/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
40	Windshield // Repair	Y
83	Door Front Left // Painting	Y
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	Y
136	Bumper Rear // Polish	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

## Damage Pictures



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Polish-scratch




Wing Rear Left // Painting-scratch



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Bumper Front // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Windshield // Repair-glass damage