

INSPECTION REPORT


End of contract

GENERAL INFO

File	314038
License plate	XY4807
Vehicle identification number	VR3USHNSSNJ662339
Dossier	2021342043
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	34949
First registration	26/07/2022
client availability date	29/05/2026
inspectionDate	02/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	N
72	Side View Mirror Left // Painting	Y
86	Door Front Left // Polish	Y
92	Rocker Panel Left // Painting	Y
106	Door Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
180	Wing Rear Right // Smart Repair Small	Y
214	Door Front Right // Repair & Painting	N
282	Bumper Rear / Trim Center / Replace	N
340	Wheel Two Tone Front Right // Repair	Y

Damage Pictures



Door Front Left // Polish-scratch



Bumper Rear / Trim Center / Replace-scratch



Bumper Rear // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Side View Mirror Left // Painting-scratch



Door Rear Left // Polish-scratch




Rocker Panel Left // Painting-scratch



Wing Rear Right // Smart Repair Small-dent



Door Front Right // Repair & Painting-scratch + dent



Front Bonnet / Insulation / Replace-tear