

INSPECTION REPORT


End of contract

GENERAL INFO

File	321361
License plate	2BPY565
Vehicle identification number	VF3MCYHZMMS267452
Dossier	2021245097
Make	Peugeot 3008 1.5BHDi 96kW Road
Mileage	146286
First registration	09/02/2022
client availability date	09/09/2026
inspectionDate	18/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
32	Front Bonnet // Painting	Y
72	Side View Mirror Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
310	Wheel Two Tone Front Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
413	Seat Front Left / Rear Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
641	Rear Right Door Interior Coating // Repair	Y
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Rocker Panel Left // Smart Repair Medium-scratch



Interior / Side Cover rear Seat / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Right Door Interior Coating // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front // Painting-scratch



Front Bonnet // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Left // Painting-scratch



Seat Front Left / Rear Coating / Replace-worn



Seat Front Left / Bottom Coating / Replace-worn