

INSPECTION REPORT


End of contract

GENERAL INFO

File	307559
License plate	2DMN589
Vehicle identification number	VR3USHNKKPJ592126
Dossier	2022294042
Make	Peugeot 2008 1.2 74kW Active P
Mileage	62592
First registration	26/04/2023
client availability date	09/03/2026
inspectionDate	13/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
213	Door Front Right // Painting	N
217	Door Front Right / Trim / Replace	N
81	Door Front Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	N
117	Wing Rear Left / Trim / Replace	N
139	Bumper Rear / Spoiler / Replace	N
153	Rear Bonnet // Painting	N
222	Side View Mirror Right // Painting	N
223	Side View Mirror Right // Replace Not Painted	Y

Damage Pictures





Damage within Renta-norm-scratch



Door Rear Left // Repair & Painting-scratch + dent



Rear Bonnet // Painting-scratch



Bumper Rear / Spoiler / Replace-scratch




Wing Rear Left / Trim / Replace-scratch



Door Front Left // Smart Repair Medium-scratch



Side View Mirror Right // Replace Not Painted-scratch



Side View Mirror Right // Painting-scratch



Wing Rear Right / Trim / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Painting-scratch



Door Front Right / Trim / Replace-scratch