

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	315691
License plate	LG1980
Vehicle identification number	ZARPAHDN3N7D46034
Dossier	2022206001
Make	Alfa Romeo Stelvio 2.0T280 AWD
Mileage	123864
First registration	28/07/2022
client availability date	18/06/2026
inspectionDate	23/06/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





## DAMAGES

Damages	Type	Acceptable
72	Side View Mirror Left // Painting	N
80	Door Front Left // Smart Repair Small	Y
114	Wing Rear Left // Repair & Painting	Y
222	Side View Mirror Right // Painting	N
341	Wheel Alloy Front Right // Repair	N
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
860	Interior Cleaning // Small	N

## Damage Pictures



Wheel Alloy Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain



Interior // Repair 1-worn



Side View Mirror Right // Painting-Chipped paint



Side View Mirror Left // Painting-Chipped paint