

INSPECTION REPORT

End of contract

GENERAL INFO

File	320270
License plate	ZN8976
Vehicle identification number	TMBJJ8NX7PY096789
Dossier	2021127008
Make	Skoda Octav.Comb TDi150 Style
Mileage	111427
First registration	21/03/2023
client availability date	14/08/2026
inspectionDate	18/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
136	Bumper Rear // Polish	Y
154	Rear Bonnet // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	N
201	Rocker Panel Right // Smart Repair Medium	Y
562	Dashboard / Instruments Panel / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Rocker Panel Right // Smart Repair Medium-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Bumper Rear // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Rear Bonnet // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain



Dashboard / Instruments Panel / Replace-N comf / out of order