

INSPECTION REPORT


End of contract

GENERAL INFO

File	308250
License plate	2BRF612
Vehicle identification number	W1K1771861J348079
Dossier	2021286101
Make	Mercedes A Berline 250e PHEV B
Mileage	90916
First registration	23/02/2022
client availability date	23/03/2026
inspectionDate	03/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
221	Side View Mirror Right // Plastic Repair	N
228	Side View Mirror Right / Direction Indicator / Replace	N
13	Bumper Front // Painting	N
54	Headlight / Front left / Replace	N
35	Front Bonnet // Polish	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
167	Roof / Roof Rails / Replace	Y
184	Wing Rear Right // Repair & Painting	N
274	Bumper Front / Grid Central / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
431	Seat Rear Left // Repair	Y
774	Interior / Side Cover rear Seat / Replace	N

Damage Pictures






Damage within Renta-norm-



Bumper Front / Grid Central / Replace-bad position




Roof / Roof Rails / Replace-bad position



Wing Rear Right // Repair & Painting-scratch + dent



Light / Rear Left On Rear Bonnet / Replace-scratch



Front Bonnet // Polish-scratch



Interior / Side Cover rear Seat / Replace-scratch



Seat Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right // Plastic Repair-scratch



Bumper Front // Painting-scratch



Headlight / Front left / Replace-bad position