

INSPECTION REPORT



End of contract


GENERAL INFO

File	320823
License plate	2ATW001
Vehicle identification number	W1K1771121J322017
Dossier	2020308044
Make	Mercedes A Berline 200 d Bus.S
Mileage	151495
First registration	14/07/2021
client availability date	24/08/2026
inspectionDate	04/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
83	Door Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	N
113	Wing Rear Left // Painting	N
133	Bumper Rear // Painting	Y
181	Wing Rear Right // Smart Repair Medium	Y
274	Bumper Front / Grid Central / Replace	Y
631	Rear Left Door Interior Coating // Repair	N
644	Rear Right Door Interior Coating // Replace Completely	N
860	Interior Cleaning // Small	N

Damage Pictures



Bumper Rear // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Rear Left Door Interior Coating // Repair-scratch



Bumper Front // Smart Repair Medium-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Wing Rear Right // Smart Repair Medium-scratch



Door Front Left // Painting-scratch



Wing Rear Left // Painting-bad repair



Door Rear Left // Painting-bad repair



Interior Cleaning // Small-stain



Bumper Front / Grid Central / Replace-bad position