

INSPECTION REPORT


End of contract

GENERAL INFO

File	319826
License plate	2BXR946
Vehicle identification number	YV1XZBWVFN2776457
Dossier	2021 316 033
Make	Volvo XC40 T4 PHEV Inscript.Ex
Mileage	100063
First registration	03/05/2022
client availability date	07/08/2026
inspectionDate	17/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	Y
104	Door Rear Left // Repair & Painting	Y
136	Bumper Rear // Polish	Y
156	Rear Bonnet // Polish	Y
196	Door Rear Right // Polish	Y
210	Door Front Right // Smart Repair Small	Y
234	Wing Front right // Repair & Painting	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures



Rear Bonnet // Polish-scratch



Bumper Rear // Polish-scratch



Door Rear Right // Polish-scratch



Door Front Right // Smart Repair Small-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Front Left // Polish-scratch



Bumper Front // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Door Rear Left // Repair & Painting-scratch + dent



Wing Front right // Repair & Painting-scratch + dent



Front Bonnet // Polish-Chemical reaction



Interior Cleaning // Small-stain