



ARVAL
BNP PARIBAS GROUP

2GCS182

INSPECTION REPORT

End of contract

GENERAL INFO

File	318207
License plate	2GCS182
Vehicle identification number	W1N4M8HBXSW391239
Dossier	2024295090
Make	Mercedes GLB 200 AMG Line
Mileage	84490
First registration	28/10/2024
client availability date	23/07/2026
inspectionDate	25/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
61	Wing Front Left // Smart Repair Medium	N
67	Wing Front Left / Trim / Replace	N
83	Door Front Left // Painting	N
87	Door Front Left / Trim / Replace	Y
107	Door Rear Left / Trim / Replace	Y
117	Wing Rear Left / Trim / Replace	N
132	Bumper Rear // Smart Repair Large	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
16	Bumper Front // Polish	Y
41	Windshield // Replace	N
104	Door Rear Left // Repair & Painting	N
153	Rear Bonnet // Painting	Y
156	Rear Bonnet // Polish	Y
157	Rear Bonnet / Trim / Replace	Y
165	Roof // Polish	Y
182	Wing Rear Right // Smart Repair Large	N
193	Door Rear Right // Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
211	Door Front Right // Smart Repair Medium	Y
217	Door Front Right / Trim / Replace	Y
225	Side View Mirror Right // Polish	Y
310	Wheel Two Tone Front Left // Repair	Y
316	Tyre Front Left // Replace	N
330	Wheel Two Tone Rear Right // Repair	Y
346	Tyre Front Right // Replace	N
411	Seat Front Left // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures



Seat Front Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Front Right // Smart Repair Medium-scratch



Door Front Right / Trim / Replace-scratch



Bumper Front // Polish-scratch



Windshield // Replace-scratch





Door Rear Left // Repair & Painting-scratch + dent



Wing Rear Right // Smart Repair Large-scratch + dent



Side View Mirror Right // Polish-Chemical reaction



Interior Cleaning // Small-dirty




Tyre Front Right // Replace-worn



Tyre Front Left // Replace-worn



Rear Bonnet // Polish-scratch



Roof // Polish-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Door Rear Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Trim / Replace-scratch



Rear Bonnet // Painting-scratch



Wing Front Left // Smart Repair Medium-scratch



Wing Front Left / Trim / Replace-scratch



Door Front Left // Painting-scratch



Door Rear Left / Trim / Replace-worn



Door Front Left / Trim / Replace-worn



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Smart Repair Large-scratch



Wing Rear Left / Trim / Replace-scratch