

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	283001
License plate	1WDQ521
Vehicle identification number	WAUZZZF40KA075240
Dossier	2018 345 043
Make	Audi A4 Av.35 TDi 150 Str.Bus.
Mileage	104259.00
First registration	06/05/2019
	06/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
112	Wing Rear Left // Smart Repair Large	N
133	Bumper Rear // Painting	N
182	Wing Rear Right // Smart Repair Large	N
192	Door Rear Right // Smart Repair Large	N
208	Rocker Panel Right / Cover Not Painted / Replace	N
335	Wheel Rear Right / Hub Cover with Logo / Replace	N
432	Seat Rear Left / Bottom Coating / Replace	Y
452	Seat Rear Right / Bottom Coating / Replace	Y

Damage Pictures



Rocker Panel Right / Cover Not Painted / Replace-scratch



Seat Rear Right / Bottom Coating / Replace-dent




Seat Rear Left / Bottom Coating / Replace-dent



Wing Rear Left // Smart Repair Large-scratch + dent



Bumper Rear // Painting-scratch + dent



Door Rear Right // Smart Repair Large-scratch + dent



Bumper Front // Painting-scratch + dent



Wing Rear Right // Smart Repair Large-scratch + dent



Wheel Rear Right / Hub Cover with Logo / Replace-missing