

INSPECTION REPORT

End of contract

GENERAL INFO

File	311262
License plate	2BUV518
Vehicle identification number	KMHC851CGNU285764
Dossier	2021 249 034
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	119513
First registration	30/03/2022
client availability date	22/04/2026
inspectionDate	06/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
35	Front Bonnet // Polish	Y
103	Door Rear Left // Painting	N
107	Door Rear Left / Trim / Replace	N
113	Wing Rear Left // Painting	Y
132	Bumper Rear // Smart Repair Large	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N

Damage Pictures



Wing Rear Left // Painting-scratch



Door Rear Left / Trim / Replace-scratch



Door Rear Left // Painting-scratch




Front Bonnet // Polish-scratch



Bumper Front // Smart Repair Large-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Bumper Rear // Smart Repair Large-scratch + dent