

INSPECTION REPORT


End of contract

GENERAL INFO

File	319964
License plate	1YXU642
Vehicle identification number	W1N1671171A351424
Dossier	2020 253 021
Make	Mercedes GLE 350 de 4M
Mileage	229552
First registration	26/01/2021
client availability date	17/08/2026
inspectionDate	28/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
72	Side View Mirror Left // Painting	N
84	Door Front Left // Repair & Painting	Y
100	Door Rear Left // Smart Repair Small	Y
136	Bumper Rear // Polish	Y
193	Door Rear Right // Painting	Y
233	Wing Front right // Painting	Y
320	Wheel Two Tone Rear Left // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
413	Seat Front Left / Rear Coating / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures




Side View Mirror Left // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch




Door Rear Left // Smart Repair Small-scratch




Bumper Rear // Polish-scratch



Door Rear Right // Painting-scratch




Wing Front right // Painting-scratch




Door Front Left // Repair & Painting-dent





Interior Cleaning // Small-dirty



Seat Front Left / Bottom Coating / Replace-worn



Seat Front Left / Rear Coating / Replace-worn