

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	307580
License plate	2BCG716
Vehicle identification number	TMBJH9NP2N7012561
Dossier	2021048098
Make	Skoda Sup.Comb.TDi 150 Clever+
Mileage	99865
First registration	29/09/2021
client availability date	09/03/2026
inspectionDate	13/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
64	Wing Front Left // Repair & Painting	N
41	Windshield // Replace	N
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	N
184	Wing Rear Right // Repair & Painting	Y
196	Door Rear Right // Polish	Y
213	Door Front Right // Painting	N
234	Wing Front right // Repair & Painting	Y
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	N
860	Interior Cleaning // Small	N

## Damage Pictures



Damage within Renta-norm-scratch






Wing Rear Right // Repair & Painting-scratch + dent



Windshield // Replace-glass damage



Interior Cleaning // Small-stain




Wheel Alloy Front Right // Repair-scratch



Door Front Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Rear Right // Polish-scratch




Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Painting-scratch



Wing Front right // Repair & Painting-scratch + dent



Bumper Front // Painting-scratch



Wing Front Left // Repair & Painting-scratch + dent