

INSPECTION REPORT


End of contract


GENERAL INFO

File	311545
License plate	62221
Vehicle identification number	W1N2533111G032182
Dossier	2022011002
Make	Mercedes GLC Coupé 300de 4M B.
Mileage	49143
First registration	21/01/2022
client availability date	27/04/2026
inspectionDate	29/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
237	Wing Front right / Trim / Replace	Y
543	Interior // Ionization Odor	N
560	Interior / A Pillar Cover / Replace	N
569	Dashboard / Steering Wheel / Replace	Y

Damage Pictures



Wing Front right / Trim / Replace-scratch



Bumper Rear // Painting-bad repair



Interior / A Pillar Cover / Replace-Incinerated



Dashboard / Steering Wheel / Replace-worn

