

INSPECTION REPORT


End of contract


GENERAL INFO

File	316607
License plate	TX8882
Vehicle identification number	W1K1771871J374102
Dossier	2022081020
Make	Mercedes A Sedan 200 163 AMG L
Mileage	33627
First registration	27/06/2022
client availability date	30/06/2026
inspectionDate	02/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
54	Headlight / Front left / Replace	N
60	Wing Front Left // Smart Repair Small	N
71	Side View Mirror Left // Plastic Repair	N
86	Door Front Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	Y
124	Light / Rear left / Replace	N
165	Roof // Polish	Y
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	Y
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Left // Plastic Repair-scratch



Door Front Left // Polish-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Wheel Two Tone Rear Left // Repair-scratch



Light / Rear left / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Painting-scratch




Door Rear Right // Painting-scratch



Side View Mirror Right // Painting-scratch



Door Front Right // Repair & Painting-scratch + dent



Roof // Polish-Chemical reaction



Wheel Two Tone Front Right // Repair-scratch



Headlight / Front left / Replace-scratch



Bumper Front // Painting-scratch



Wing Front Left // Smart Repair Small-scratch