

INSPECTION REPORT


End of contract

GENERAL INFO

File	319766
License plate	2ADJ424
Vehicle identification number	W0V7D9EE9L4449255
Dossier	2021050142
Make	Opel Crossland X 1.2 61kW Edit
Mileage	75399
First registration	26/02/2021
client availability date	07/08/2026
inspectionDate	21/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	
		N	
		N	
		N	
		N	







DAMAGES

Damages	Type	Acceptable
802	See External Expertise 2	N

Damage Pictures



See External Expertise 2-



Damage within Renta-norm-