

INSPECTION REPORT


End of contract

GENERAL INFO

File	306399
License plate	2BUU676
Vehicle identification number	ZFANF2C34MP953613
Dossier	2022 068 066
Make	Fiat 500X 1.0 FT 115 Yacht Clu
Mileage	121586
First registration	30/03/2022
client availability date	04/03/2026
inspectionDate	11/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
40	Windshield // Repair	Y
106	Door Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
194	Door Rear Right // Repair & Painting	N
310	Wheel Two Tone Front Left // Repair	N
332	Wheel Alloy Rear Right // Replace	N

Damage Pictures





Damage within Renta-norm-



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left // Polish-scratch




Bumper Rear // Polish-scratch



Wheel Alloy Rear Right // Replace-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Windshield // Repair-glass damage