

INSPECTION REPORT


End of contract

GENERAL INFO

File	306843
License plate	2CHL253
Vehicle identification number	W1KAH5EB5PF067260
Dossier	2022 103 003
Make	Mercedes C Break 300e 230kW Lu
Mileage	115577
First registration	29/07/2022
client availability date	05/03/2026
inspectionDate	16/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
330	Wheel Two Tone Rear Right // Repair	N
336	Tyre Rear Right // Replace	N
101	Door Rear Left // Smart Repair Medium	Y
320	Wheel Two Tone Rear Left // Repair	N

Damage Pictures





Damage within Renta-norm-



Door Rear Left // Smart Repair Medium-scratch + dent



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Tyre Rear Right // Replace-tear