

INSPECTION REPORT

End of contract

GENERAL INFO

File	317160
License plate	ZG5707
Vehicle identification number	YV1LFH7V5R1236754
Dossier	2024117002
Make	Volvo XC90 T8 310 Plus Br.AWD
Mileage	71603
First registration	05/06/2024
client availability date	02/07/2026
inspectionDate	06/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
131	Bumper Rear // Smart Repair Medium	N
187	Wing Rear Right / Trim / Replace	N
12	Bumper Front // Smart Repair Large	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
273	Bumper Front / Grid Left / Replace	N
274	Bumper Front / Grid Central / Replace	N
78	Side View Mirror Left / Direction Indicator / Replace	N
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
184	Wing Rear Right // Repair & Painting	N
196	Door Rear Right // Polish	Y
237	Wing Front right / Trim / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Wing Rear Right // Repair & Painting-scratch + dent



Wheel Two Tone Rear Right // Repair-scratch



Wing Front right / Trim / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch




Door Rear Right // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Rear Right / Trim / Replace-scratch



Bumper Rear // Smart Repair Medium-scratch



Bumper Front // Smart Repair Large-scratch



Bumper Front / Grid Left / Replace-dent



Bumper Front / Grid Central / Replace-dent



Bumper Front / Lower Cover Not Painted / Replace-scratch + dent