

INSPECTION REPORT

End of contract

GENERAL INFO

File	306639
License plate	1YDX571
Vehicle identification number	YV1ZZARVCM1066485
Dossier	2020 042 178
Make	Volvo V60 D3 Cross Country Gtr
Mileage	207139
First registration	30/07/2020
client availability date	02/03/2026
inspectionDate	12/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
257	Front / Towing Cover / Replace	N
18	Bumper Front / Spoiler / Replace	N
40	Windshield // Repair	Y
101	Door Rear Left // Smart Repair Medium	N
174	Light / Rear Right / Replace	Y
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
411	Seat Front Left // Repair	N
421	Seat Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures







Damage within Renta-norm-



Windshield // Repair-glass damage






Interior Cleaning // Small-stain



Bumper Front / Spoiler / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Seat Front Right // Repair-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Seat Front Left // Repair-scratch



Light / Rear Right / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Door Rear Left // Smart Repair Medium-scratch + dent



Bumper Front // Painting-bad repair



Front / Towing Cover / Replace-bad repair