

INSPECTION REPORT

End of contract

GENERAL INFO

File	320720
License plate	BU6076
Vehicle identification number	W1K1770121V145359
Dossier	2022033005
Make	Mercedes A 200 d 150 Business
Mileage	142323
First registration	11/08/2022
client availability date	24/08/2026
inspectionDate	27/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
40	Windshield // Repair	Y
54	Headlight / Front left / Replace	N
78	Side View Mirror Left / Direction Indicator / Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
124	Light / Rear left / Replace	Y
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
184	Wing Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
883	Key Price Range 2 //	N

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Bumper Rear // Polish-scratch



Light / Rear left / Replace-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Headlight / Front left / Replace-scratch



Bumper Front // Smart Repair Medium-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Left // Smart Repair Medium-dent



Door Front Right // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Windshield // Repair-cracked