

INSPECTION REPORT


End of contract

GENERAL INFO

File	307908
License plate	2CNZ725
Vehicle identification number	TMBJR8NX3PY029311
Dossier	2022039025
Make	Skoda Oct.Com.1.5TSI 110kW Cle
Mileage	199632
First registration	03/10/2022
client availability date	17/03/2026
inspectionDate	19/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
41	Windshield // Replace	Y
81	Door Front Left // Smart Repair Medium	Y
93	Rocker Panel Left // Repair & Painting	N
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
161	Roof // Smart Repair Medium	N
184	Wing Rear Right // Repair & Painting	Y
216	Door Front Right // Polish	Y

Damage Pictures



Damage within Renta-norm-Chemical reaction



Bumper Front // Painting-scratch





Door Front Right // Polish-scratch





Wing Rear Left // Polish-scratch



Door Rear Left // Polish-scratch




Door Front Left // Smart Repair Medium-scratch



Roof // Smart Repair Medium-dent




Rocker Panel Left // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Bumper Rear // Painting-bad repair



Windshield // Replace-cracked