

INSPECTION REPORT


End of contract

GENERAL INFO

File	322568
License plate	2CFC675
Vehicle identification number	W1K2130121B088693
Dossier	2021329148
Make	Mercedes E 200 d 118kW Bus.Sol
Mileage	116766
First registration	30/06/2022
client availability date	17/09/2026
inspectionDate	29/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
40	Windshield // Repair	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
183	Wing Rear Right // Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
240	Headlight / Front Right/ Repair	N
340	Wheel Two Tone Front Right // Repair	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N


Damage Pictures



Wing Rear Left // Polish-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Medium-scratch



Windshield // Repair-scratch



Headlight / Front Right/ Repair-scratch



Bumper Front // Painting-scratch



Bumper Rear // Painting-scratch




Wheel Two Tone Front Right // Repair-scratch



Rocker Panel Right // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-dent



Wing Rear Right // Painting-scratch + dent



Interior Cleaning // Small-stain