

INSPECTION REPORT

End of contract

GENERAL INFO

File	303625
License plate	2CFX174
Vehicle identification number	W1N1671171A708040
Dossier	2022 172 071
Make	Mercedes GLE 350 de 4M Bus.Sol
Mileage	96694
First registration	08/07/2022
client availability date	02/03/2026
inspectionDate	04/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
136	Bumper Rear // Polish	Y
185	Wing Rear Right // Replace & Painting	Y
174	Light / Rear Right / Replace	N
175	Light / Rear Right On Rear Bonnet / Replace	N
32	Front Bonnet // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
124	Light / Rear left / Replace	N
159	Rear Bonnet / Rear Window / Replace	N
227	Side View Mirror Right / Shell / Replace Not Painted	N
272	Bumper Front / Trim Right / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	Y
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
614	Front Left Door Interior Coating // Replace Completely	Y
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures






Damage within Renta-norm-scratch



Light / Rear left / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Front Bonnet // Painting-scratch



Bumper Front / Trim Right / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch




Side View Mirror Right / Shell / Replace Not Painted-scratch



Front Left Door Interior Coating // Replace Completely-scratch



Rear Right Door Interior Coating // Repair-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent




Interior // Repair 1-Incinerated



Tyre Front Right // Replace-tear



Interior Cleaning // Small-stain



Rear Bonnet / Rear Window / Replace-scratch




Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Replace & Painting-scratch



Bumper Rear // Polish-scratch



Light / Rear Right / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch