

INSPECTION REPORT


End of contract

GENERAL INFO

File	315074
License plate	2AUL360
Vehicle identification number	W1N2476121W135615
Dossier	2020 310 073
Make	Mercedes GLB 200d Business Sol
Mileage	103582
First registration	22/07/2021
client availability date	11/06/2026
inspectionDate	16/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	








DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
124	Light / Rear left / Replace	N
133	Bumper Rear // Painting	N
13	Bumper Front // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
201	Rocker Panel Right // Smart Repair Medium	N
213	Door Front Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures




See External Expertise-




Wheel Two Tone Rear Left // Repair-scratch




Wheel Two Tone Front Left // Repair-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rocker Panel Left // Smart Repair Medium-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent




Interior Cleaning // Small-dirty



Dashboard / Steering Wheel / Replace-worn



Bumper Front // Painting-stone chipping




Wheel Alloy Front Right // Repair-scratch



Door Front Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Painting-scratch



Light / Rear left / Replace-scratch