

INSPECTION REPORT

End of contract

GENERAL INFO

File	314037
License plate	XY4757
Vehicle identification number	VR3USHNSSNJ662348
Dossier	2021342060
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	44506
First registration	26/07/2022
client availability date	29/05/2026
inspectionDate	02/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
32	Front Bonnet // Painting	N
41	Windshield // Replace	Y
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	Y
89	Door Front Left / Window / Replace	Y
109	Door Rear Left / Window / Replace	Y
117	Wing Rear Left / Trim / Replace	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
187	Wing Rear Right / Trim / Replace	Y
190	Door Rear Right // Smart Repair Small	Y
213	Door Front Right // Painting	N
244	Light / Front Right / Replace	N
320	Wheel Two Tone Rear Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N


Damage Pictures



Door Front Left / Window / Replace-scratch



Door Rear Left / Window / Replace-scratch



Rear Bonnet // Polish-scratch




Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Right / Trim / Replace-scratch




Light / Front Right / Replace-scratch



Bumper Front // Painting-scratch



Windshield // Replace-scratch



Side View Mirror Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Door Front Left / Trim / Replace-scratch



Wing Rear Left / Trim / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch



Door Rear Right // Smart Repair Small-dent



Door Front Right // Painting-bad repair



Front Bonnet // Painting-Chemical reaction



Interior Cleaning // Small-stain