

INSPECTION REPORT

End Of Contract


GENERAL INFO

File	288058
License plate	PH9843
Vehicle identification number	WAUZZZF3XM1053725
Dossier	2020280002
Make	Audi Q3 40TDi 200 S line Quatt
Mileage	109870.00
First registration	08/12/2020
	04/07/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
67	Wing Front Left / Trim / Replace	N
271	Bumper Front / Trim Left / Replace	N
28	Front / Calendar / Replace	Y
87	Door Front Left / Trim / Replace	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
180	Wing Rear Right // Smart Repair Small	N
194	Door Rear Right // Repair & Painting	N
222	Side View Mirror Right // Painting	N
311	Wheel Alloy Front Left // Repair	N

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Door Front Left / Trim / Replace-scratch



Wheel Alloy Front Left // Repair-scratch




Front / Calendar / Replace-scratch



Side View Mirror Right // Painting-scratch



Wing Rear Right // Smart Repair Small-dent




Door Rear Right // Repair & Painting-scratch + dent



Wing Front Left / Trim / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Smart Repair Medium-scratch