

INSPECTION REPORT





End of contract

GENERAL INFO

File	307822
License plate	2DAD214
Vehicle identification number	TMBLJ7NU7P5020709
Dossier	2022033138
Make	Skoda Karoq 2.0CRTDI 110kW C.4
Mileage	125518
First registration	11/01/2023
client availability date	16/03/2026
inspectionDate	24/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
83	Door Front Left // Painting	Y
106	Door Rear Left // Polish	Y
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
153	Rear Bonnet // Painting	Y
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	N
236	Wing Front right // Polish	Y
540	Interior // Repair 1	Y
540	Interior // Repair 1	N
883	Key Price Range 2 //	N

Damage Pictures





Damage within Renta-norm-



Wing Front right // Polish-scratch



Front Bonnet // Polish-scratch




Interior // Repair 1-scratch



Interior // Repair 1-tear



Wing Rear Right // Polish-scratch




Rear Bonnet // Painting-scratch



Bumper Rear // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Rear Left // Polish-scratch



Door Front Left // Painting-scratch



Door Rear Right // Painting-scratch + dent