

INSPECTION REPORT



End of contract

GENERAL INFO

File	314643
License plate	2DKW475
Vehicle identification number	TMBJG8NX1PY116243
Dossier	2022165210
Make	Skoda Oct.Com.2.0TDI 85kW Clev
Mileage	48254
First registration	12/04/2023
client availability date	05/06/2026
inspectionDate	12/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	N
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y


Damage Pictures




Bumper Rear // Painting-scratch



Door Rear Left // Polish-scratch



Wing Rear Left // Polish-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Windshield // Replace-glass damage