

INSPECTION REPORT




End of contract


GENERAL INFO

File	321167
License plate	2BAC038
Vehicle identification number	VXKUPHNEKM4207528
Dossier	2021 137 017
Make	Opel Corsa 1.2 100 Elegance 5d
Mileage	89907
First registration	03/09/2021
client availability date	09/09/2026
inspectionDate	19/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
81	Door Front Left // Smart Repair Medium	Y
116	Wing Rear Left // Polish	Y
150	Rear Bonnet // Smart Repair Small	Y
159	Rear Bonnet / Rear Window / Replace	N
161	Roof // Smart Repair Medium	Y
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
540	Interior // Repair 1	Y
569	Dashboard / Steering Wheel / Replace	Y

Damage Pictures



Door Front Left // Smart Repair Medium-scratch



Wing Rear Left // Polish-scratch




Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Roof // Smart Repair Medium-dent



Rear Bonnet // Smart Repair Small-dent



Dashboard / Steering Wheel / Replace-worn

