

INSPECTION REPORT

End of contract

GENERAL INFO

File	306977
License plate	1YTF257
Vehicle identification number	VF3MCYHZRLS251956
Dossier	2020 174 020
Make	Peugeot 5008 1.5BHDi 96kW GT L
Mileage	133485
First registration	07/12/2020
client availability date	13/03/2026
inspectionDate	18/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	N
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
228	Side View Mirror Right / Direction Indicator / Replace	N
624	Front Right Door Interior Coating // Replace Completely	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
680	Keys Detachable Towing Hook //	N

Damage Pictures





Damage within Renta-norm-





Side View Mirror Right / Direction Indicator / Replace-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Rocker Panel Right // Smart Repair Medium-scratch





Front Bonnet // Polish-scratch



Door Rear Left // Smart Repair Medium-dent



Rear Left Door Interior Coating // Replace Completely-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent

