

INSPECTION REPORT


End of contract

GENERAL INFO

File	321354
License plate	BU6089
Vehicle identification number	W1N2476121W241151
Dossier	2022052005
Make	Mercedes GLB 200d 150 Business
Mileage	106523
First registration	30/08/2022
client availability date	02/09/2026
inspectionDate	07/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
91	Rocker Panel Left // Smart Repair Medium	N
150	Rear Bonnet // Smart Repair Small	N
159	Rear Bonnet / Rear Window / Replace	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N

Damage Pictures



Door Rear Right // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent