

INSPECTION REPORT

End of contract

GENERAL INFO

File	310840
License plate	2CSL086
Vehicle identification number	JTDKBABB20A133196
Dossier	2022145205
Make	Toyota Yar.Cr.1.5 Hyb.85kw Dyn
Mileage	67797
First registration	10/11/2022
client availability date	17/04/2026
inspectionDate	22/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
67	Wing Front Left / Trim / Replace	N
78	Side View Mirror Left / Direction Indicator / Replace	Y
84	Door Front Left // Repair & Painting	N
103	Door Rear Left // Painting	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	N
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	N
202	Rocker Panel Right // Painting	Y
216	Door Front Right // Polish	Y
314	Wheel Front Left / Wheel Cover / Replace	N
324	Wheel Rear Left / Wheel Cover / Replace	N
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
538	Trunk Compartment / Boot Cover / Replace	N
556	Central Console / Cover Armrest / Replace Cover Armrest	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Trunk Compartment / Boot Cover / Replace-missing



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Rear Bonnet // Polish-scratch





Bumper Rear // Painting-scratch




Wing Rear Right // Polish-scratch



Door Rear Right // Painting-scratch



Rocker Panel Right // Painting-scratch



Door Front Right // Polish-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Door Rear Left // Painting-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Wing Rear Left // Polish-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Central Console / Cover Armrest / Replace Cover Armrest-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch




Roof // Smart Repair Medium-dent



Door Front Left // Repair & Painting-scratch + dent



Wing Front Left / Trim / Replace-scratch



Bumper Front // Repair & Painting-scratch + dent