

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	309879
License plate	RF9858
Vehicle identification number	W1N9N0CBXSJ122005
Dossier	2023362008
Make	Mercedes EQA 250+ 190 Business
Mileage	29898
First registration	25/04/2024
client availability date	01/04/2026
inspectionDate	09/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	N
29	Front / Park Assist Sensor / Replace	N
231	Wing Front right // Smart Repair Medium	N
237	Wing Front right / Trim / Replace	N
272	Bumper Front / Trim Right / Replace	N
28	Front / Calendar / Replace	N
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	N
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
150	Rear Bonnet // Smart Repair Small	N
180	Wing Rear Right // Smart Repair Small	Y
191	Door Rear Right // Smart Repair Medium	N
340	Wheel Two Tone Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

## Damage Pictures



Door Rear Left // Painting-scratch + dent



Bumper Rear // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Front / Calendar / Replace-scratch




Door Front Left // Smart Repair Small-scratch



Wing Rear Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Rear Bonnet // Smart Repair Small-dent



Wing Rear Right // Smart Repair Small-dent



Door Rear Right // Smart Repair Medium-scratch + dent



Wing Front right / Trim / Replace-scratch



Wing Front right // Smart Repair Medium-scratch



Front / Park Assist Sensor / Replace-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Front // Repair & Painting-scratch + dent