

# INSPECTION REPORT


End of contract


## GENERAL INFO

File	310430
License plate	XZ6590
Vehicle identification number	ZACPJFDWXMPR86549
Dossier	2021263006
Make	Jeep Com.1.3PHEV 180 eAWD Trai
Mileage	66908
First registration	17/03/2022
client availability date	13/04/2026
inspectionDate	16/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
104	Door Rear Left // Repair & Painting	Y
113	Wing Rear Left // Painting	Y
193	Door Rear Right // Painting	Y
210	Door Front Right // Smart Repair Small	Y
346	Tyre Front Right // Replace	N

## Damage Pictures



Door Front Left // Smart Repair Small-scratch



Door Front Right // Smart Repair Small-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Repair & Painting-scratch + dent



Door Rear Right // Painting-rust



Tyre Front Right // Replace-N comf / out of order