

INSPECTION REPORT


End of contract


GENERAL INFO

File	312654
License plate	XQ7724
Vehicle identification number	VR7EFYHYCMJ693776
Dossier	2021056050
Make	Citroen Berl. MWB 1.5BHDi102 X
Mileage	182483
First registration	06/05/2021
client availability date	11/05/2026
inspectionDate	13/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
184	Wing Rear Right // Repair & Painting	Y
196	Door Rear Right // Polish	Y
13	Bumper Front // Painting	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
38	Front Bonnet / Insulation / Replace	N
64	Wing Front Left // Repair & Painting	N
80	Door Front Left // Smart Repair Small	Y
104	Door Rear Left // Repair & Painting	Y
110	Wing Rear Left // Smart Repair Small	Y
124	Light / Rear left / Replace	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
174	Light / Rear Right / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	Y
227	Side View Mirror Right / Shell / Replace Not Painted	Y
236	Wing Front right // Polish	Y
291	Rear Loading Door Left // Smart Repair Medium	Y
304	Rear Loading Door Right // Repair & Painting	Y
569	Dashboard / Steering Wheel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N


Damage Pictures



Rear Loading Door Right // Repair & Painting-scratch + dent



Front Bonnet / Insulation / Replace-tear



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Light / Rear left / Replace-scratch



Light / Rear Right / Replace-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Wing Front right // Polish-scratch



Bumper Front // Painting-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Door Front Left // Smart Repair Small-scratch




Front Right Door Interior Coating // Replace Completely-scratch



Door Front Right // Smart Repair Small-dent





Rear Loading Door Left // Smart Repair Medium-dent




Wing Front Left // Repair & Painting-dent



Wing Rear Left // Smart Repair Small-dent



Door Rear Left // Repair & Painting-scratch + dent



Door Rear Right // Polish-scratch



Wing Rear Right // Repair & Painting-scratch + dent