

# INSPECTION REPORT

**End of contract**

## GENERAL INFO

|                               |                        |
|-------------------------------|------------------------|
| File                          | 320894                 |
| License plate                 | 2FMF262                |
| Vehicle identification number | W1K2050131R586546      |
| Dossier                       | 2019270045             |
| Make                          | Mercedes C 300 de Aut. |
| Mileage                       | 100393                 |
| First registration            | 24/06/2020             |
| client availability date      | 26/08/2026             |
| inspectionDate                | 02/09/2026             |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | Y       |        |
| Charge back wrong tyres   |        | N       |        |






## DAMAGES

| Damages | Type                                                   | Acceptable |
|---------|--------------------------------------------------------|------------|
| 12      | Bumper Front // Smart Repair Large                     | N          |
| 78      | Side View Mirror Left / Direction Indicator / Replace  | N          |
| 83      | Door Front Left // Painting                            | N          |
| 104     | Door Rear Left // Repair & Painting                    | Y          |
| 136     | Bumper Rear // Polish                                  | Y          |
| 156     | Rear Bonnet // Polish                                  | Y          |
| 184     | Wing Rear Right // Repair & Painting                   | Y          |
| 186     | Wing Rear Right // Polish                              | Y          |
| 216     | Door Front Right // Polish                             | Y          |
| 228     | Side View Mirror Right / Direction Indicator / Replace | N          |
| 310     | Wheel Two Tone Front Left // Repair                    | N          |
| 320     | Wheel Two Tone Rear Left // Repair                     | N          |
| 326     | Tyre Rear Left // Replace                              | N          |
| 330     | Wheel Two Tone Rear Right // Repair                    | N          |
| 340     | Wheel Two Tone Front Right // Repair                   | Y          |
| 346     | Tyre Front Right // Replace                            | N          |

## Damage Pictures



Wing Rear Right // Polish-scratch



Bumper Rear // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front // Smart Repair Large-scratch




Wheel Two Tone Front Left // Repair-scratch




Side View Mirror Left / Direction Indicator / Replace-scratch



Door Front Right // Polish-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Door Front Left // Painting-bad repair



Rear Bonnet // Polish-Chemical reaction



Tyre Rear Left // Replace-tear



Tyre Front Right // Replace-tear