

INSPECTION REPORT


End of contract

GENERAL INFO

File	320053
License plate	SF4032
Vehicle identification number	W1K3F8EB0SJ460637
Dossier	2024033010
Make	Mercedes A 180 Business Line A
Mileage	69532
First registration	17/05/2024
client availability date	12/08/2026
inspectionDate	17/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
40	Windshield // Repair	Y
87	Door Front Left / Trim / Replace	Y
92	Rocker Panel Left // Painting	Y
106	Door Rear Left // Polish	Y
107	Door Rear Left / Trim / Replace	Y
114	Wing Rear Left // Repair & Painting	Y
134	Bumper Rear // Repair & Painting	N
154	Rear Bonnet // Repair & Painting	Y
162	Roof // Painting	N
169	Rear Bonnet / Spoiler / Replace & Painting	Y
190	Door Rear Right // Smart Repair Small	Y
316	Tyre Front Left // Replace	Y
340	Wheel Two Tone Front Right // Repair	N
536	Trunk Compartment / Cover Storage Tray / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Rear Bonnet / Spoiler / Replace & Painting-scratch



Door Rear Left // Polish-scratch



Door Rear Left / Trim / Replace-scratch



Door Front Left / Trim / Replace-scratch



Rocker Panel Left // Painting-scratch





Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch




Door Rear Right // Smart Repair Small-dent




Trunk Lid Interior Coating / Complete Panel / Replace-scratch + dent




Rear Bonnet // Repair & Painting-scratch + dent




Bumper Rear // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Windshield // Repair-glass damage



Roof // Painting-Chemical reaction



Tyre Front Left // Replace-worn



Trunk Compartment / Cover Storage Tray / Replace-N
comf / out of order