

INSPECTION REPORT


End of contract

GENERAL INFO

File	310506
License plate	DW6870
Vehicle identification number	W1N1673541A544600
Dossier	2021035013
Make	Mercedes GLE Coupe 350e 211 4M
Mileage	93255
First registration	11/11/2021
client availability date	14/04/2026
inspectionDate	17/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
87	Door Front Left / Trim / Replace	Y
107	Door Rear Left / Trim / Replace	Y
186	Wing Rear Right // Polish	Y
188	Wing Rear Right / Fuel Cover / Replace	Y
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
187	Wing Rear Right / Trim / Replace	N
13	Bumper Front // Painting	Y
35	Front Bonnet // Polish	Y
41	Windshield // Replace	Y
54	Headlight / Front left / Replace	Y
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	N
110	Wing Rear Left // Smart Repair Small	N
124	Light / Rear left / Replace	Y
154	Rear Bonnet // Repair & Painting	N
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	Y
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
228	Side View Mirror Right / Direction Indicator / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	Y
421	Seat Front Right // Repair	Y

594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	N

Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch




Light / Rear Right / Replace-scratch



Light / Rear left / Replace-scratch



Door Front Right // Polish-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch





Wheel Two Tone Front Right // Repair-scratch



Windshield // Replace-scratch



Headlight / Front left / Replace-scratch



Front Bonnet // Polish-scratch




Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Right // Repair-scratch



Seat Front Left // Repair-scratch



Rear Left Door Interior Coating // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch




Wing Rear Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Rocker Panel Right // Smart Repair Medium-dent



Rear Bonnet // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Bumper Front // Painting-stone chipping



Door Front Left / Trim / Replace-scratch



Door Rear Left / Trim / Replace-scratch



Wing Rear Right // Polish-scratch



Wing Rear Right / Fuel Cover / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch





Bumper Rear // Painting-scratch



Wing Rear Right / Trim / Replace-scratch