

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	306910
License plate	2AKP154
Vehicle identification number	W1N1671171A441570
Dossier	2020 318 102
Make	Mercedes GLE 350 de 4M
Mileage	162612
First registration	27/04/2021
client availability date	15/05/2026
inspectionDate	28/05/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	





## DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	N
150	Rear Bonnet // Smart Repair Small	N
165	Roof // Polish	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
310	Wheel Two Tone Front Left // Repair	Y
316	Tyre Front Left // Replace	N
340	Wheel Two Tone Front Right // Repair	N

## Damage Pictures





Damage within Renta-norm-



Light / Rear left / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Wheel Two Tone Front Left // Repair-scratch




Bumper Rear // Painting-scratch





Wheel Two Tone Front Right // Repair-scratch



Rear Bonnet // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Roof // Polish-Chemical reaction



Tyre Front Left // Replace-tear