

INSPECTION REPORT

End of contract

GENERAL INFO

File	317421
License plate	CM8448
Vehicle identification number	W1N1671171A703852
Dossier	2021342121
Make	Mercedes GLE 350de 194 4M Aut
Mileage	55548
First registration	14/06/2022
client availability date	06/07/2026
inspectionDate	08/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
84	Door Front Left // Repair & Painting	N
187	Wing Rear Right / Trim / Replace	Y
194	Door Rear Right // Repair & Painting	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wing Rear Right / Trim / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent

