

INSPECTION REPORT

End of contract

GENERAL INFO

File	309845
License plate	1YKA795
Vehicle identification number	W1K1771031J264125
Dossier	2019344107
Make	Mercedes A Berline 180 d Bus.S
Mileage	158966
First registration	17/09/2020
client availability date	06/04/2026
inspectionDate	10/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	Y
80	Door Front Left // Smart Repair Small	N
103	Door Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
186	Wing Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	Y
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
413	Seat Front Left / Rear Coating / Replace	Y
540	Interior // Repair 1	Y
569	Dashboard / Steering Wheel / Replace	Y

Damage Pictures



Bumper Rear // Painting-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Two Tone Front Left // Repair-scratch




Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Smart Repair Small-scratch



Wing Rear Right // Polish-scratch



Bumper Front // Smart Repair Large-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent



Front Bonnet // Polish-bad repair



Wing Front right // Polish-bad repair



Wing Front Left // Polish-bad repair



Dashboard / Steering Wheel / Replace-worn



Interior // Repair 1-worn



Seat Front Left / Rear Coating / Replace-worn