

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	283085
License plate	1YWD525
Vehicle identification number	WAUZZZF56MA019721
Dossier	2020183089
Make	Audi A5 SB 30 TDi 100kW Bu.E.A
Mileage	108685.00
First registration	08/01/2021
	02/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
31	Front Bonnet // Smart Repair Small	N
136	Bumper Rear // Polish	Y
183	Wing Rear Right // Painting	N
193	Door Rear Right // Painting	N
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N

Damage Pictures




Bumper Front // Smart Repair Large-scratch



Wheel Alloy Front Right // Repair-scratch




Door Rear Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch




Wing Rear Right // Painting-scratch



Bumper Rear // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Front Bonnet // Smart Repair Small-dent