

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	314258
License plate	XY4788
Vehicle identification number	VR3USHNSSNJ662268
Dossier	2021342083
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	63469
First registration	30/06/2022
client availability date	02/06/2026
inspectionDate	04/06/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





## DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
236	Wing Front right // Polish	Y
184	Wing Rear Right // Repair & Painting	N
196	Door Rear Right // Polish	N
35	Front Bonnet // Polish	Y
38	Front Bonnet / Insulation / Replace	N
66	Wing Front Left // Polish	Y
104	Door Rear Left // Repair & Painting	Y
136	Bumper Rear // Polish	Y
187	Wing Rear Right / Trim / Replace	N
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
340	Wheel Two Tone Front Right // Repair	N
860	Interior Cleaning // Small	N

## Damage Pictures



Front Bonnet / Insulation / Replace-tear





Interior Cleaning // Small-stain




Wheel Two Tone Front Right // Repair-scratch




Bumper Rear // Polish-scratch



Wing Rear Right / Trim / Replace-scratch




Front Bonnet // Polish-scratch




Side View Mirror Right // Painting-scratch



Wing Front Left // Polish-scratch



Door Rear Left // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Wing Front right // Polish-scratch



Bumper Front // Polish-scratch



Door Rear Right // Polish-scratch



Wing Rear Right // Repair & Painting-scratch + dent